








MONK L











R




L




A  H-120 4x	B  H-50 2x	C  H-120 4x	D  5x30 16x	E  M6x15 2x
F  M6x15 2x	G  2x	H  6x		

E		F		G	
M6x15		2x	M6x15	2x	2x





1




R






L

A		B		C		D		H	
H-120		1x	H-50	2x	H-120	2x	5x30	8x	3x


2




A 	C 	D 	H 
H-120	3x H-120	2x 5x30	8x 3x

3





L



R



4



5

